

Radon Inspection Report

Measurement of Radon Concentration in Indoor Air

Report No.: 2700005918201803261620 Report Generated Date: 3/26/18
 Serial No.: 2700005918

Measurement Address:

Saratoga Springs 12866

Measurement performed by:

Steven Grimaldi
 Adirondack Healthy Home

Ventilation: -

Building type: -

Building year: -

Room	Floor	Measurement Start	Measurement End	Measured Value
-	-	3/15/18, 11:40 AM	3/17/18, 11:40 AM	16.1 pCi/L

Comments:

Saratoga Springs March 26, 2018

Location

Date

Signature

Detailed Measurement Data


	Min	Max	Average
Radon [pCi/L]	9.4	25.4	16.1
Temperature [°F]	63.7	70.2	66.4
Humidity [%rH]	32	35	34
Pressure [kPa]	98.72	100.08	99.42

Table of hourly radon measurements for hour 1 to hour 48

Timestamp	Radon values
Hr: 1 - 12:40 PM	15.0
Hr: 2 - 1:40 PM	17.9
Hr: 3 - 2:40 PM	18.7
Hr: 4 - 3:40 PM	18.7
Hr: 5 - 4:40 PM	15.8
Hr: 6 - 5:40 PM	15.5
Hr: 7 - 6:40 PM	14.1
Hr: 8 - 7:40 PM	16.5
Hr: 9 - 8:40 PM	13.7
Hr: 10 - 9:40 PM	15.5
Hr: 11 - 10:40 PM	15.8
Hr: 12 - 11:40 PM	24.7
Hr: 13 - 12:40 AM	13.6
Hr: 14 - 1:40 AM	19.1
Hr: 15 - 2:40 AM	16.2
Hr: 16 - 3:40 AM	13.6
Hr: 17 - 4:40 AM	13.7
Hr: 18 - 5:40 AM	11.5
Hr: 19 - 6:40 AM	13.4
Hr: 20 - 7:40 AM	9.7
Hr: 21 - 8:40 AM	13.1
Hr: 22 - 9:40 AM	11.6
Hr: 23 - 10:40 AM	12.0
Hr: 24 - 11:40 AM	12.6

Timestamp	Radon values
Hr: 25 - 12:40 PM	15.9
Hr: 26 - 1:40 PM	18.9
Hr: 27 - 2:40 PM	18.4
Hr: 28 - 3:40 PM	22.0
Hr: 29 - 4:40 PM	25.4
Hr: 30 - 5:40 PM	23.8
Hr: 31 - 6:40 PM	24.0
Hr: 32 - 7:40 PM	23.8
Hr: 33 - 8:40 PM	19.8
Hr: 34 - 9:40 PM	15.6
Hr: 35 - 10:40 PM	21.1
Hr: 36 - 11:40 PM	17.4
Hr: 37 - 12:40 AM	18.2
Hr: 38 - 1:40 AM	13.2
Hr: 39 - 2:40 AM	9.4
Hr: 40 - 3:40 AM	14.4
Hr: 41 - 4:40 AM	11.5
Hr: 42 - 5:40 AM	12.7
Hr: 43 - 6:40 AM	10.4
Hr: 44 - 7:40 AM	12.7
Hr: 45 - 8:40 AM	15.3
Hr: 46 - 9:40 AM	13.0
Hr: 47 - 10:40 AM	15.9
Hr: 48 - 11:40 AM	16.2

Radon and Movement Chart



Humidity and Temperature Chart

